

REPORT OF CHANNEL CONDITIONS (FOR CHANNELS 400 FEET WIDE OR GREATER) (EP 1130-2-520)						PAGE 1 OF PAGES 1		
TO: Navigation Interests						FROM: U.S. Army Engineer District, Baltimore P.O. Box 1715 Baltimore, Maryland 21203-1715		
RIVER/HARBOR NAME AND STATE Curtis Bay Channel Baltimore Harbor, Maryland						MINIMUM DEPTHS IN EACH 1/4 WIDTH OF CHANNEL ENTERING FROM SEAWARD		
NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MID-CHANNEL		
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)		LEFT INSIDE QUARTER (feet)	RIGHT INSIDE QUARTER (feet)	RIGHT OUTSIDE QUARTER (feet)
Curtis Bay Channel	30 Jan 2006	600	2.07	50	49.4	49.6	49.5	49.2
REMARKS <i>(Continue on reverse)</i> All depths refer to mean lower low water for the 1983 to 2001 tidal epoch. This information represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.								